

Plug-in CTs

- No leads supplied with these CTs (RJ45 connection cable)
- For technical data, see page 2.48.

Description	Cat ref.
125A Frame Size 60A 3 Phase CT	EC1260CT
125A Frame Size 100A 3 Phase CT	EC12100CT
125A Frame Size 125A 3 Phase CT	EC12125CT
125A Frame Size 160A 3 Phase CT	EC12160CT
250A Frame Size 60A 3 Phase CT	EC2560CT
250A Frame Size 100A 3 Phase CT	EC25100CT
250A Frame Size 125A 3 Phase CT	EC25125CT
250A Frame Size 160A 3 Phase CT	EC25160CT
250A Frame Size 200A 3 Phase CT	EC25200CT
250A Frame Size 250A 3 Phase CT	EC25250CT
400A Frame Size 250A 3 Phase CT	EC40250CT
400A Frame Size 400A 3 Phase CT	EC40400CT
400A Frame Size 630A 3 Phase CT	EC40630CT
800A Frame Size 800A 3 Phase CT	EC80800CT



EC1260CT

3 Phase CT Splitter Box

- This 3 Phase CT Splitter Box allows the separate monitoring of each phase of a three phase current transformer on individual energy meters.
- For technical data, see page 2.49.

Description	Cat ref.
3 Phase CT Splitter Box	JFS03



JFS03

Meter Voltage Supply Cable - Low Smoke Zero Halogen - 1mm

Description	Cat ref.
1m - Voltage Supply Cable with Fuse Carrier (For JF Meter Enclosures)	JF130VMF
1m - Voltage Supply Cable with Fuse Carrier (For JN Meter Enclosures)	JN130VMF



PGM500

Meter Voltage Supply Cable - PVC - 1mm

Description	Cat ref.
0.30m - Hi Flex Voltage Supply Cable	PGMF300
0.50m - Hi Flex Voltage Supply Cable	PGMF500
1.00m - Hi Flex Voltage Supply Cable	PGMF1000
1.30m - Hi Flex Voltage Supply Cable	PGMF1300
2.00m - Hi Flex Voltage Supply Cable	PGMF2000
3.00m - Hi Flex Voltage Supply Cable	PGMF3000

Meter to Meter Supply Cable - PVC - 1mm

Description	Cat ref.
0.15m - Hi Flex Meter to Meter Supply Cable	PGMFT150
0.30m - Hi Flex Meter to Meter Supply Cable	PGMFT300
0.50m - Hi Flex Meter to Meter Supply Cable	PGMFT500
1.00m - Hi Flex Meter to Meter Supply Cable	PGMFT1000
1.30m - Hi Flex Meter to Meter Supply Cable	PGMFT1300
2.00m - Hi Flex Meter to Meter Supply Cable	PGMFT2000
3.00m - Hi Flex Meter to Meter Supply Cable	PGMFT3000