

## Magnetic Strap

- Frees up hands to help work safely
- Fits 490/480/340 Series Multimeters



Description	Cat. No.
Magnetic Strap	61-565

## USB Cable

- Provides safe, easy measurement of AC current
- Extends the current measurement capabilities of digital multimeters
- AC milli-volt output (1mVAC = 1mA)



Description	Cat. No.
Optical USB Cable for 490 Series Meters & Software	61-902

## Current Clamp Adapter

Description	Cat. No.
600A AC/DC Clamp Adapter - 2 ft. lead length	61-334



### Specifications

61-334	
AC Current	1 – 600 A
DC Current	1 – 600 A
Output Signal	1mV/A
Max Conductor Size	1.125" (28.5cm)



## Flexible Clamp Adapter

- Provides safe, easy measurement of high AC currents
- Large opening and flexible materials to wrap around conductors and bus bars
- Shape Memory allows pre-forming before installation
- Extends the current measurement capabilities of digital multimeters



Description	Cat. No.
300/3000AAC Flexible Clamp Adapter	61-331

### Specifications

61-331	
AC Current	300/3000A
DC Current	—
Output Signal	1mV/A/10mV/A
Max Conductor Size	8" (19cm)
Sensor Length	36" (91cm)

## Test Leads



Description	Cat. No.
Premium Test Leads w/alligator clips	TL-100
Silicone Test Leads	TL-102
Test Leads w/large alligator clip	TL-104
Fused Test Leads w/alligator clips, 10A/600V, CAT III - 1000V	TLF-252