



Powering Business Worldwide





Instruction Leaflet
Montageanweisung
Notice d'installation
Instrucciones de montaje
Istruzioni per il montaggio
安装说明
Инструкция по монтажу
Montagehandleiding

Montagevejledning
Οδηγίες εγκατάστασης
Instruções de montagem
Monteringsanvisning
Asennusohje
Návod k montáži
Paigaldusjuhend
Szerelési utasítás


Montāžas instrukcija
Montavimo instrukcija
Instrukcja montażu
Navodila za montažo
Návod na montáž
Монтажни инструкции
Instrucțiuni de montaj
Upute za montažu

Kullanma Talimatı
Инструкция за монтаж
Instruksjonsblad
Монтажна інструкція
نشرة التعليمات

RCCB and MCBs




green zielony
vert grön
zelený grön
zelený vihreä
grøn yeşil
verde verde
zöld зелена
verde πράσινος
grønn πράσινο
groen 綠色
groen أخضر




OFF

red czerwony
rouge ród
červený punainen
rød kırmızı
rojo roşu
vörös црвена
rosso κόκκινος
rød 红色
rood أحمر



ON




2 - 2,4Nm



Twist!

1,5 - 35mm² Cu only
2,5 - 35mm²
Flexible Cu cable
without ferrule



Extension for RCD's:

Maximum back-up fuse

$I_n = 16-63A$

$I_n = 80A$

$I_n = 100A$

Short circuit

63 A gG/gL

80 A gG/gL

100 A gG/gL

