



C1600 Gear Box for meter and accessories

A rugged, molded plastic case with a deep interior and lift-out tray designed to carry Fluke handheld digital multimeters and process calibrators, as well as their accessories. Features a large handle and snap-open lid compartment for easy access to small parts such as fuses, batteries, probes, and leads. Can also be locked.

- Includes five hook and loop straps to wrap cords and test leads
- Dimensions (HxWxD):
260 mm x 390 mm x 200 mm
(10 in x 15 in x 7.8 in)

Leather cases

C520A Leather Tester Case

Rugged leather case designed to hold Fluke electrical testers. It features a large belt loop and a top flap to secure the tester. Made of top-grain cowhide with heavy-duty stitching and reinforced rivets.

- Dimensions (HxWxD):
256 mm x 154 mm x 106 mm
(10 in x 6 in x 4 in)

C510 Leather Meter Case

Rugged leather case designed to hold most Fluke digital multimeters, thermometers, and process calibrators. It features a large belt loop and a top flap to secure the tool. Made of top-grain cowhide with heavy-duty stitching and reinforced rivets.

- Dimensions (HxWxD):
287 mm x 179 mm x 106 mm
(11 in x 7 in x 4 in)

Holsters

H5 Electrical Tester Holster

Rugged fabric holster designed to hold Fluke T3 and T5 Electrical Testers. It features a built-in belt loop and flap for test lead storage.

- Dimensions (HxWxD):
192 mm x 90 mm x 38 mm
(7.5 in x 3.5 in x 1.5 in)

H3 Clamp Meter Holster

Rugged fabric holster designed to hold Fluke 330 Series Clamp Meters. It features a built-in belt loop and a handy pocket with snap for test lead storage.

- Dimensions (HxWxD):
231 mm x 90 mm x 64 mm
(9 in x 3.5 in x 2.5 in)

New! H15 Electrical Tester Holster

Rugged fabric holster designed to hold Fluke T90, T110, T130 and T150 Two-Pole Testers.

- High quality 1000D fabric
- Dimensions (HxWxD):
27.9 cm x 9.2 cm x 5.1 cm
(11 in x 3.6 in x 2 in)

H80M Protective Holster with Magnetic Hanging Strap

Convenient snap-on holster with a magnetic hanging system enables hands-free work while protecting digital multimeters or calibration tools. This holster is designed to absorb shock and to hang from just about any metal surface.

- Includes a hanging magnet, general purpose hanger, and hook and loop straps
- Dimensions (HxWxD):
190 mm x 95 mm x 43 mm
(7.5 in x 3.7 in x 1.7 in)

C10 Meter Holster

Snap-on holster absorbs shocks and protects multimeters from rough handling. It features a built-in stand and hanger loop for convenience during testing.

- Compatible with Fluke 10 Series Multimeters
- Dimensions (HxWxD):
154 mm x 77 mm x 45 mm
(6 in x 3 in x 1.8 in)

H6 Infrared Thermometer Holster

Durable nylon construction with Velcro® closures provides quick access and protection for infrared thermometers. It features a snap-open loop that attaches easily to a belt and an accessory pocket for storing temperature probes.

- Dimensions (HxWxD):
302 mm x 178 mm x 57 mm
(11.9 in x 7 in x 2 in)



H15



H80M



C520A



C510



H5



H3



H6



C10