

MESSING
KLEMMEN, NIET
GEÏSOLEERD

START KABELS



056206

564015

056404

056190

056602

			 $\approx \varnothing$ CU	
056206	320 A	3 m	16 mm ²	
564015	500 A	3 m	25 mm ²	
056404	700 A	4.5 m	35 mm ²	
056190	1000 A	4.5 m	50 mm ² (100% Cu)	
056602	1000 A	5.1 m	50 mm ² (100% Cu)	

MADE in PRC

www.gys.fr