




5902305901

Wood Turning Lathe
DM600VARIO
scheppach - 220-240V
50Hz 550W



Main products

5902305901

Spare part list

135123 - 0110 - DM600Vario - -

Spare	Description	additional	Item	Abb.	ConstructStatus
5902305001	adjust knob	RAL9005	1	A	*
3902303002	Tail spindle assy.	Gewindestange M16	4-6,47,59	A	*
5902305002	front cover of tail		8	A	*
5902305003	rear cover of tail		10	A	*
5902305004	lever assy		11,12,14,15,26	A	*
5902305005	base cover		16	A	*
5902305006	Base		17	A	*
01091314	Threaded Pin	M5x8 DIN913 ST blank	18	A	*
5902305007	seat of tool Carrie assy		18,20-27,62	A	*



5902305901

Wood Turning Lathe
DM600VARIO
scheppach - 220-240V
50Hz 550W



Main products

Spare part list

5902305901

135123 - 0110 - DM600Vario - -

Spare	Description	additional	Item	Abb.	ConstructStatus
5902305008	tool carrier assy		28-30	A	*
5902305009	speed controlling knob		31	A	*
3902303011	switch	KR55/2, 15A, 250VAC	32	A	*
5902305010	front cover of nose		33, 64	A	*
5902305016	connector of speed knob	B50K	34	A	*
5902305011	motor left housing		35	A	*
5902305012	motor right housing		36	A	*
5902305013	rear cover of nose		37, 65	A	*
3902303016	Rotor		40	A	*
3902303017	Stator		41	A	*
3902303018	carbon brush set (= 2 pcs.)		44	A	*
3902303019	main shaft	M18x1,5	54	A	*
3902303020	disc chuck	M18x1,5	56	A	*
3902303021	head spindle		57	A	*
3902102025	key SW 24	SW 24	61	A	*
3902303022	PCB of regualting speed		63	A	*
5902305014	front cover-2		64	A	*
5902305015	rear cover -2		65	A	*
7902300702	chisel kit PDM600A1		o.Abb.	A	*

!!! Do you know: From now on you can view spare parts lists in our spare parts shop and order spare parts and accessories directly. More information can be found here: <https://www.scheppach.com/Shop.aspx>